


Make:	Isuzu	Model:	D-MAX	Body Style:	Utility
Year:	2019	Registration:	MFY310	Reg Expiry:	21 Jul 2024
WoF Expiry:	29 Jul 2025	Odometer:	72,472 Kms	Good No:	23023803
VIN:	MPATFS85JKT002977	Next Service:	84000km	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

All good.

Interior Comments

Seats	Good
Carpets	Average
Panels	Good
Dashboard	average as screw holes from previous attachments

General Comments

Vehicle drove well.
Unsure if winch works, rope in back of vehicle.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓