


<b>Make:</b>	Mitsubishi	<b>Model:</b>	Pajero Sport	<b>Body Style:</b>	SUV
<b>Year:</b>	2020	<b>Registration:</b>	MTH35	<b>Reg Expiry:</b>	18 Nov 2024
<b>WoF Expiry:</b>	13 May 2025	<b>Odometer:</b>	119,326 Kms	<b>Good No:</b>	23034696
<b>VIN:</b>	MMAGUKS10LH00203	<b>Next Service:</b>	130,000	<b>Service History:</b>	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Drivers mirror casings broken. Centre lhs head rest missing. Front bumper lower skirt broken and held in place with cable ties. Rear badge damaged. Vehicle very dirty at inspection time. Stone chips in front screen

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Tested battery and passed. Vehicle has belly pans. Runs on diesel fuel

**Interior Comments**

Seats	Average
Carpets	wearing thin
Panels	scuffs scratches marks
Dashboard	scratches

**General Comments**

Air conditioning and heating work fine at inspection time

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	8.0	mm	
Right front	8.0	mm	
Left rear	8.0	mm	
Right rear	8.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Gary Adams

Date: 11 Jun 2024

I have read and understood this condition guide.

Name: .....

Signature: .....