

Basic Vehicle Condition Guide

Report ID: 23,034,758


Version: 2

20 Jun 2024 Created:

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2019 Registration: LZP706 Reg Expiry: 12 Sep 2024 WoF Expiry: **Odometer: Good No:** 14 Mar 2025 150,093 Kms 23034758 VIN: MR0JA3DD100345216 Next Service: 165,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Brake fluid low. Runs on diesel fuel

Interior Comments			
Seats	marks		
Carpets	Average		
Panels	scuffs scratches marks		
Dashboard	scratches		

General Comments

Air conditioning and heating work fine at inspection time

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

11 Jun 2024 Inspected by: Gary Adams Date:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	\ \ \				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	<i>v v</i>				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	8	.0	mm		
Right front	8.0		mm		
Left rear	8.0		mm		
Right rear	8.0		mm		
Spare		Yes			
Suspension		ı			
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	-				
Electrical / Accessories					
Head lights	•				
Tail lights	/				
Indicators	•				
Dashboard warning lights	•				
Wipers (front & rear) Window winder FL	\(\times \)				
Window winder FL Window winder FR	<i>V</i>				
	V				
Window winder RL Window winder RR	\(\times \)				
Rear view mirrors	•				
Radio (basic test only)	<i>v</i>				
CD (basic test only)	<i>v</i>				
Number of keys					
Central locking	3				
Remote locking	1				
Sat. Nav. (basic test only)			V		
Reversing camera	V				
eversing curriera					

I have read and understood this condition guide.

Name:

Signature: