

Report ID: 23,050,172 Version: 1 16 Dec 2024 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	MEF43	Reg Expiry:	26 May 2025	Engine			I
WoF Expiry:		Odometer:	310,999 Kms	Good No:	23050172	Oil level	~		
VIN:	7AT0H60FX19023319	Next Service:	313200	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
	W				S D	Performance	~		
Key:		-0	s sc	-01-	30	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SC DE			715	HILS	Operation	~		
PT = paint defe		F		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					R SC	Clutch	~		
P = pin dent	LIDE HID				74114	CV joints	~		
* = decals	SDSC 91			The second	BID SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	t scuffs W		S D S D SC		S D	Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	depth	of tyre	es)
Rust around windscreen						Left front			
Minor stone	e chips on windscreen					Right front	5.	0	mm
						Left rear	4.	0	mm
Conditions During Body Inspection: Dry						Right rear	3.	5	mm
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear wheel	drivo					Suspension performance	~		
Rear wheel	unve					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Seats Stains, Drivers seat torn.					Head lights	~		
						Tail lights	~		
Carpets	Rear dama	iged, Front good				Indicators	~		
Panels	Rear dama	iged, Front good				Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Rear water jet not operating						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 28	80,000	Reversing camera	~		
Increased by Javkib Collins									
Inspected by: Jaykib Collins Date: 16 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....