

Report ID: 23,050,473 Version: 1 20 Dec 2024 Created:

Make:	BMW	Model:	X3	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	Registration:	LNT129	Reg Expiry:	29 Sep 2024	Engine	1	I	
WoF Expiry:	08 Oct 2025	Odometer:	157,891 Kms	Good No:	23050473	Oil level	~		
VIN:	WBAWZ520400K90072	Next Service:	167000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Consid		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC		S D P SC		S D	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack					SC	Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs SC PSC SPSC SPSC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Indicator missing from LF guard,roof racks,						Left front 2.7 m			mm
						Right front	4	.8	mm
						Left rear	6	.6	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Cood					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Drives okay,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicmy						Remote locking	~		
Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Donovan Matara Date: 11 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: