

## **Basic Vehicle Condition Guide**

Report ID: 23,050,500


Version: 3

Created: 06 Jan 2025

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2021 Registration: NPR448 Reg Expiry: 13 Jan 2025 **Odometer:** WoF Expiry: **Good No:** 14 Jul 2025 41,749 Kms 23050500 **Next Service:** VIN: KMHS281KSMU381726 56700km Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

## **General Comments**

4WD.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Haden Brown Date: 09 Dec 2024

		1	
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<b>v</b>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	7	.0	mm
Right front	7.0		mm
Left rear	4.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	!	ļ	1
Operation 🗸			
Electrical / Accessories	l		1
Head lights	~		
Tail lights			
Indicators	<b>V</b>		
Dashboard warning lights	~		
Wipers (front & rear)	<ul><li>V</li><li>V</li></ul>		
Window winder FL	~		
Window winder FR	<b>1</b>		
Window winder RL	<i>'</i>		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	·		
Remote locking	~		
Sat. Nav. (basic test only)	<u> </u>		<b>V</b>
Reversing camera	<b>1</b>		
neversing cumera		1	1

I have read and understood this condition guide.

Name: .....

Signature: .....