

Basic Vehicle Condition Guide

Report ID: 23,050,912


Version: 4

Created: 12 Dec 2024

Make: Model: Hyundai lload **Body Style:** Van Year: 2017 Registration: KRM992 Reg Expiry: 27 Mar 2025 **Odometer:** WoF Expiry: **Good No:** 15 Aug 2025 149,818 Kms 23050912 VIN: KMFWBX7KLHU905422 Next Service: 150000km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Rear Wheel Drive.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Haden Brown Date: 05 Dec 2024

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	v v			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission		!		
Operation	~			
Noise	~			
Clutch	\(\times \) \(\t			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	6	.0	mm	
Right front	7	.0	mm	
Left rear	7	.0	mm	
Right rear	7.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	\(\times \)			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL			~	
Window winder RR			~	
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2		1	
Central locking				
Remote locking	'		<u> </u>	
Sat. Nav. (basic test only)			~	
Reversing camera				

Signature: