

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance SP P Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S S SC Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ S P SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs D SP Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 4 **Right front** 4 mm Left rear 6 mm **Right rear** mm Conditions During Body Inspection: 6 Dry Spare Under Carriage & Under Bonnet Inspection Comments Suspension FWD Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V 1 key for doors 2 keys for ignition. Window winder RR V Rear view mirrors 1 Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V

Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No

Inspected by: Eleoit Kumar

06 Dec 2024 Date:

Sat. Nav. (basic test only)

Reversing camera

Report ID: 23,051,538 Version: 2 Created: 06 Dec 2024

Pass

~

V

V

~

N/A

Fail

I have read and understood this condition guide.

Name:

Kms:

1

Signature:

~