

V Radiator / Hoses (visual) V V V V P = pin dent CV joints ~ * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs D SD Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Stone chip on windscreen (outside the CVA.) Left front mm 3.0 **Right front** 3.0 mm Left rear 3.0 mm **Right rear** 3.0 mm Conditions During Body Inspection: Wet Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories dirty and stained. Head lights Seats 1 Tail lights 1 Average Carpets Indicators ~ Average Dashboard warning lights 1 Panels Wipers (front & rear) 1 Average Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Rear Wheel Drive. Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 1 V Central locking **Road Conditions During Test Drive:** Wet Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) ~ Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera 1 19 Sep 2024 Inspected by: Haden Brown Date:

I have read and understood this condition guide.

Name:

Signature:

Report ID: 23,054,480 Version: 3 Created: 13 Nov 2024

Pass

~

V

V

V

N/A

Fail