

## **Basic Vehicle Condition Guide**

Report ID: 23,060,613


Version: 1

Created: 01 Nov 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2018 Registration: LMA882 Reg Expiry: 27 Dec 2024 WoF Expiry: **Odometer: Good No:** 26 Jun 2025 128,341 Kms 23060613 VIN: MMU148CK0KH60151 Next Service: 134000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Average		
Carpets	dirty		
Panels	Average		
Dashboard	Average		

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Darian Beyer-Way Date: 31 Oct 2024

Name: .....

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\( \triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints	\( \times \) \( \t		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	7	.5	mm
Right front	8	.0	mm
Left rear	7.5		mm
Right rear	8.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	•		
Indicators	~		
Dashboard warning lights	\( \times \)		
Wipers (front & rear)	~		
Window winder FL	<b>/</b>		
Window winder FR	•		
Window winder RL	\( \times \)		
Window winder RR			
Rear view mirrors	<b>/</b>		
Radio (basic test only)	~		
CD (basic test only)			
Number of keys	2		
Central locking	•		
Remote locking	~		_
Sat. Nav. (basic test only)			V
Reversing camera	<i>'</i>		

Signature: .....