

Basic Vehicle Condition Guide

Report ID: 23,063,344


Version: 2

Created: 13 Aug 2024

Make: Model: Holden Equinox **Body Style:** SUV Year: 2019 Registration: MHK429 Reg Expiry: 30 Jul 2025 WoF Expiry: **Odometer: Good No:** 01 Aug 2025 109,109 Kms 23063344 VIN: 3G0AX7EX0KS655590 Next Service: 119000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan Date: 06 Aug 2024

Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	y y y y y y y y y y epth		· ·
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread deleft front Right front Left rear Right rear			· ·
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear			v
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear			V
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear			·
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		~
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		~
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		~
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		~
Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		~
Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		<i>'</i>
Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		<i>'</i>
CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		<i>'</i>
Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		
Brakes Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		
Performance Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		
Hand Brake Tyres (lowest observed tread d Left front Right front Left rear Right rear	/		
Tyres (lowest observed tread d Left front Right front Left rear Right rear	√ lepth		1
Left front Right front Left rear Right rear	lepth		
Right front Left rear Right rear		of tyre	<u>:</u> s)
Left rear Right rear	3.	.0	mm
Right rear	3.0		mm
_	2.	.0	mm
Snare	2.	.0	mm
Spare		Yes	
Suspension			
Suspension performance	'		
Steering performance	'		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	'		
Electrical / Accessories			
Head lights	/		
Tail lights	'		
Indicators	/		
Dashboard warning lights	'		
Wipers (front & rear)			
Window winder FL	'		
Window winder FR	'		
Window winder RL	'		
Window winder RR	'		
Rear view mirrors	'		
Radio (basic test only)	\		
CD (basic test only)			~
Number of keys 2	2		
Central locking	<		
Remote locking	<u>'</u>		
Sat. Nav. (basic test only)			
Reversing camera	'		

I have read and understood this condition guide.

Name:

Signature: