

Report ID: 23,068,628 Version: 2 20 Jun 2024 Created:

WoF Expiry: VIN: <u>Note: This rep</u>	2012 02 Sep 2024 7AT0GF0BX21009604	Registration: Odometer:	Legacy PCN936	Body Style: Reg Expiry:	Wagon 08 Sep 2024	Engine	1	I	1
VIN: <u>Note: This rep</u>	·	•	107 100 1/						
VIN: <u>Note: This rep</u>	·		127,122 Kms	Good No:	23068628	Oil level		~	
		Next Service:	121,000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
This report is	o <mark>rt is not a warranty</mark> a guide only. Conside	aration is made	for ago and miles	a Parts have not	been dismonthed or	Noise	~		
diagnostic test	ting undertaken. The	vehicle has beer	n driven up to 50kr	n/h from cold. The	/endor recommends	Cooling System			
a full mechani	cal inspection prior to	purchase and th	his can be arranged	l for an additional c	harge.	Coolant condition	~		1
						Performance	~		1
Key:	S SC	-0	SC W SC	<u> –</u> –	sc	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			The second	Transmission			
D = dent R = rust	SC DE			215	S SC	Operation	~		
R = rust PT = paint defe				$\left[ \left( \right) \right]$		Noise		~	
C = crack				$+ \mathbf{\nabla}$	SC	Clutch		-	~
P = pin dent	HID			$\rightarrow$	74 <u>11</u>	CV joints	~		
* = decals	sc 916					Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	scutts SC W		SC PT			Performance	~		
Dadulaan		Note: som	ne defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						<b>Tyres</b> (lowest observed tread depth of ty			es)
Stone chips left wing mirror,						Left front 4.5 m			
						Right front		.5	mm
						Left rear	6		mm
Conditions During Body Inspection: Wet						Right rear	5		mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No oil on dip	ostick at time of inspec	tion				Suspension performance	~		1
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			-
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights		~	
Carpets	6000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)		~	1
Dashboar	d Good					Window winder FL	~		
						Window winder FR	~		1
General Comments					Window winder RL	~		1	
Rear wiper blade needs replacing Right rear window not working from master switch						Window winder RR	~		1
Stereo not powering on					Rear view mirrors	~		1	
Left brake lig Whine in rea	ght not working or diff					Radio (basic test only)		~	1
while in rea						CD (basic test only)		~	1
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
Road Cond						Remote locking	~		1
							1	<u> </u>	1
Engine Tin	ning Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Engine Tin	ning Mechanism: of Cam Belt Replac	-	Lhain Iot Applicable	Kms:		Sat. Nav. (basic test only) Reversing camera			<ul><li></li><li></li><li></li></ul>
Engine Tin	of Cam Belt Replac	-		Kms:		. ,.			-

I have read and understood this condition guide.

Name: .....

Signature: .....