


<b>Make:</b> Mitsubishi	<b>Model:</b> L300	<b>Body Style:</b> Van
<b>Year:</b> 2005	<b>Registration:</b> CNW63	<b>Reg Expiry:</b> 11 Jul 2024
<b>WoF Expiry:</b> 01 Feb 2025	<b>Odometer:</b> 293,961 Kms	<b>Good No:</b> 23070411
<b>VIN:</b> JMASNP04V4A801015	<b>Next Service:</b> unknown	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

- Chrome in right headlight worn.
- Tail lights cracked.
- Bent & rusty roof gutters.
- Rear door not opening.
- Chipped windscreen.
- Jack & tools not found.
- Aerial broken.
- Rust on drivers side floor.
- Rusty areas around whole van.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

- Under body rust.
- Engine & gearbox oil leaks.
- Large hole in exhaust tail pipe.

**Interior Comments**

Seats	Drivers seat ripped.
Carpets	Cut out on drivers side.
Panels	Average
Dashboard	Steering wheel worn, screw holes.

**General Comments**

- Radio not tuning in.
- 2 keys, 1 for ignition & 1 for door locks.
- 5 speed manual petrol van, turned into a little camper.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt  
 Evidence of Cam Belt Replacement: Yes                      Kms: 231,700

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	7	mm	
Right front	4	mm	
Left rear	4	mm	
Right rear	4	mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors			✓
Radio (basic test only)		✓	
CD (basic test only)	✓		
Number of keys	2		
Central locking		✓	
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Daryll Timms

Date: 30 May 2024

I have read and understood this condition guide.      Name: .....                      Signature: .....