

Basic Vehicle Condition Guide

Report ID: 23,073,114


Version:

Created: 10 Jun 2024

Make: Model: Skoda Scala **Body Style:** Hatchback Year: 2019 Registration: MKB323 Reg Expiry: 17 Jun 2024 WoF Expiry: **Odometer:** 18 Sep 2024 195,363 Kms **Good No:** 23073114 VIN: TMBFK7NW2K302166: Next Service: 204,000 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor dents and scratches right inner wheel arch.

Chips and scratches right sill step plate.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Timing chain rattle on cold start

| Interior Comments | | | |
|-------------------|--|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | left rear interior door trim scratched | | |
| Dashboard | Good | | |

General Comments

Tyre pressure warning light on

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

06 May 2024 Inspected by: Dean Sinclair

Name:

| | Pass | Fail | N/A | |
|--|--------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | ~ | | | |
| Noise | | ~ | | |
| Cooling System | | 1 | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 6 | .0 | mm | |
| Right front | 6.5 | | mm | |
| Left rear | 6.5 | | mm | |
| Right rear | 4.5 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | V | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | | ~ | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | \(\times \) | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | | | |

Signature: