

Report ID: 23,078,562


Version: 1

Created: 23 Feb 2024

| Make: | Mitsubishi | Model: | Outlander | Body Style: | SUV |
|-------------|-------------------|---------------|-------------|----------------|-----------------|
| Year: | 2020 | Registration: | NDT593 | Reg Expiry: | 16 Nov 2024 |
| WoF Expiry: | 06 Nov 2024 | Odometer: | 206,106 Kms | Good No: | 23078562 |
| VIN: | JMFXTGF8WLZ011411 | Next Service: | 109,000kms | Service Histor | r y: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

R/H rear bumper tail light broken. Hatch door seal damaged. Chipped windscreen. Jack winder missing.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | | |
|-------------------|--|--|--|--|--|
| Seats | L/R headrest damaged, holes in L/F seat back. | | | | |
| Carpets | Holes in cargo area & drivers side carpets. | | | | |
| Panels | Scratches in cargo area, rear doors & seat panels. | | | | |
| Dashboard | Scratches. | | | | |

General Comments

Cargo barrier fitted, 3rd row seats bolted down. 7 seater 2WD petrol SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Daryll Timms Inspected by:

Name:

| | Dass | Fail | N/A |
|------------------------------|--------------|---------|------|
| Engine Engine | Pass | Ган | IN/A |
| Oil level | | | |
| Smoke & fumes | • | | |
| Performance | v v | | |
| Noise | • | | |
| Cooling System | | | |
| Coolant condition | | | |
| Performance | | | |
| Radiator / Hoses (visual) | • | | |
| Transmission | | | |
| Operation | ., | | |
| Noise | • | | |
| Clutch | | | |
| CV joints | | | |
| Wheel bearings | | | |
| Brakes | <i>V</i> | | |
| Performance | | | |
| Hand Brake | - | | |
| Tyres (lowest observed tread | d donth | of ture | 22) |
| Left front | · · | | |
| | | 2 | mm |
| Right front Left rear | | 3 | mm |
| | | 4 - | mm |
| Right rear Spare | : | 5 V | mm |
| Suspension | | Yes | |
| Suspension performance | | | |
| Steering performance | • | | |
| Shock absorbers | • | | |
| Air Conditioning / Heater | | | |
| Operation Operation | | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | • | | |
| Window winder FL | ~ | | |
| Window winder FR | <i>V</i> | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | • | | |
| Radio (basic test only) | • | | |
| CD (basic test only) | | | - |
| Number of keys | 2 | | |
| Central locking | • | | |
| Remote locking | • | | |
| | | | |
| Sat. Nav. (basic test only) | | | - |
| Reversing camera | | | |

23 Feb 2024

Signature:

Date: