

| | | |
|--------------------------------|----------------------------------|--------------------------------|
| Make: Ford | Model: Falcon | Body Style: Sedan |
| Year: 2011 | Registration: LBS987 | Reg Expiry: 14 Jun 2025 |
| WoF Expiry: 09 Feb 2025 | Odometer: 199,444 Kms | Good No: 23091324 |
| VIN: 6FPAAAJG5WAR60081 | Next Service: 208,000 Kms | Service History: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
 S = scratch
 D = dent
 R = rust
 PT = paint defect
 C = crack
 P = pin dent
 * = decals
 SC = stone chips
 W = significant scuffs

Body Inspection Comments
 Note: some defects & blemishes may not be displayed in the diagram
 Dent in front left A-Pillar
 Front right low beam headlight isn't working

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments
 Transmission oil seep

Interior Comments

| | |
|-----------|---|
| Seats | Front seats have slight wear, rear seats good |
| Carpets | Wear on drivers side |
| Panels | Good |
| Dashboard | Good |

General Comments
 Interior roof lining is sagging

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
 Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 4.8 | mm | |
| Right front | 5.2 | mm | |
| Left rear | 3.1 | mm | |
| Right rear | 3.8 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | | ✓ | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

Inspected by: Hoani Saunders Date: 11 Sep 2024

I have read and understood this condition guide. Name: Signature: