

## **Basic Vehicle Condition Guide**

Report ID: 23,798,233


Version: 4

Created: 21 Aug 2024

Make: Model: Nissan Leaf **Body Style:** Hatchback Year: 2017 Registration: **QBH368 Reg Expiry:** 29 Dec 2024 WoF Expiry: **Odometer:** 21 Aug 2025 60,406 Kms **Good No:** 23798233 VIN: 7AT0DH8KX23008255 Next Service: N/A Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Fail N/A Pass Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 4.6 mm Left rear 4.0 mm Right rear 4.3 mm Spare N/A Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) / Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

I have read and understood this condition guide.

Hoani Saunders

Name <sup>,</sup>	

21 Aug 2024

Date: