

Report ID: 23,809,270 6 Version: 12 Dec 2024 Created:

Make: Ni	lissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A
Year: 20	018	<b>Registration:</b>	QAW750	<b>Reg Expiry:</b>	03 Jan 2025	Engine			
WoF Expiry: 22	2 Nov 2025	Odometer:	86,477 Kms	Good No:	23809270	Oil level			~
VIN: 7/	AT0DH8KX2201270(	Next Service:	Unknown	Service Histor	y: No	Smoke & fumes			~
						Performance	~		
	o <mark>rt is not a warranty</mark> auide only. Conside	ration is made	for age and mileage	. Parts have not	been dismantled or	Noise			~
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanica	al inspection prior to	purchase and tr	his can be arranged to	or an additional c	narge.	Coolant condition	~		
	SC S		SC	S		Performance	~		
Key:		=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210	HIVS	Operation	~		
PT = paint defect	I NM				11111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	ISC DR				24116	CV joints	~		
* = decals				10	ELD SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significant se	S					Performance	~		
Body Inspe	ction Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front	3.0 mm		mm	
						Right front	3.	.5	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Wet						Right rear	6.5 mm		mm
Vict						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboard	Good					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
88.09% SOH as of 1\5\24.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence of	Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Caleb Spicer Lee Date: 31 Oct 2024									
Inspected by. Cares spicer Lee Date: 51 Oct 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....