

Report ID: 23,871,152 Version: 1 22 Nov 2024 Created:

Make:	Suzuki	Model:	lgnis	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	QCL803	Reg Expiry:	31 Jul 2025	Engine			L
WoF Expiry:	21 Feb 2025	Odometer:	92,081 Kms	Good No:	23871152	Oil level		~	
VIN:	7AT0GKDTX23138954	Next Service:	No Sticker	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	ical inspection prior to	purchase and u	his can be arranged to	r an additional C	.narge.	Coolant condition	~		
	SC		S SC W			Performance	~		
Key: S = scratch						Radiator / Hoses (visual)	~		
						Transmission			
R = rust SSCW						Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTY .		Clutch			~
P = pin dent	DSC DE				24116	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
, significan	SC		S W S W		SC	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Stone chip in windscreenn						Tyres (lowest observed tread depth of tyres)			es)
						Left front 5		5	mm
						Right front	5 mm		mm
						Left rear	6 mm		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive, Engine oil at hal	fway				Suspension performance	~		
						Steering performance	<		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dealahaa	Good					Wipers (front & rear)		~	
Dashboa	ra					Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
Front & real	wipers need replacing					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	2		
						CD (basic test only)			٢
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	<		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Andre Richardson Date: 22 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....