

Report ID: 24,521,842 Version: 3 16 Sep 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	Registration:	QFP15	Reg Expiry:	16 Nov 2024	Engine	1		I
WoF Expiry:		Odometer:	137,048 Kms	Good No:	24521842	Oil level	~		
VIN:	7AT0GF09X23030502	Next Service:	146,671 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	protion is made	for any and miles	Parts have not	boop dismonthed an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S L	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s blb			TIN	EII S	Operation	~		
R = rust PT = paint defe				í In		Noise	~		
C = crack				+		Clutch			~
P = pin dent						CV joints	~		•
* = decals	616				ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	s may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	1010.3011			ayea in the diagram		•	oftyre))
					Tyres (lowest observed tread depth of tyres) Left front 6				
							6		mm
						Right front	6		mm
						Left rear	5 mm		-
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	N/A		
Fwd	inage a onder bor	meenspeede	<u>Comments</u>			Suspension			
FWU						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	riveruge					Head lights	~		
Carpets	Average					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
	d huu Maulau Franci					D-1- 166- 20	24		
Inspected by: Marlon Espena Date: 16 Sep 2024									

I have read and understood this condition guide.

Name:

Signature: