

| | | |
|--------------------------------|-----------------------------|--------------------------------|
| Make: LDV | Model: V80 | Body Style: Van |
| Year: 2018 | Registration: LQL335 | Reg Expiry: 26 Aug 2025 |
| WoF Expiry: 26 Feb 2025 | Odometer: 77,237 Kms | Good No: 24848072 |
| VIN: LSH14JTC6JA083837 | Next Service: 87,237 | Service History: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
 S = scratch
 D = dent
 R = rust
 PT = paint defect
 C = crack
 P = pin dent
 * = decals
 SC = stone chips
 W = significant scuffs

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments
 LH/R mag wheel missing
 Aftermarket box & tail lift fitted to rear

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments
 Front wheel drive
 Engine oil only just on end of dipstick!
 Note:- Vehicle too big to lift on hoist

Interior Comments

| | |
|-----------|---------|
| Seats | Average |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments
 Air-con not cold, Reverse camera not working correctly, Navigation not working, Wipers need replacing.
 Note:- Did Not Road Test due to No Oil!

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
 Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | | ✓ | |
| Smoke & fumes | | | ✓ |
| Performance | | | ✓ |
| Noise | | | ✓ |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | | | ✓ |
| Radiator / Hoses (visual) | | | ✓ |
| Transmission | | | |
| Operation | | | ✓ |
| Noise | | | ✓ |
| Clutch | | | ✓ |
| CV joints | | | ✓ |
| Wheel bearings | | | ✓ |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | | ✓ | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 9 | mm | |
| Right front | 9 | mm | |
| Left rear | 8 | mm | |
| Right rear | 3 | mm | |
| Spare | No | | |
| Suspension | | | |
| Suspension performance | | | ✓ |
| Steering performance | | | ✓ |
| Shock absorbers | | | ✓ |
| Air Conditioning / Heater | | | |
| Operation | | ✓ | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | | ✓ | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | | | ✓ |
| Window winder RR | | | ✓ |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | | ✓ | |
| Reversing camera | | ✓ | |

Inspected by: Andre Richardson Date: 13 Nov 2024

I have read and understood this condition guide. Name: Signature: