

Basic Vehicle Condition Guide

Report ID: 24,951,622


Version: 2

Created: 06 Jun 2024

Make: Model: Ford Ranger **Body Style:** Utility Year: 2019 Registration: MCK978 Reg Expiry: 23 Oct 2024 WoF Expiry: **Odometer:** 25 Aug 2024 166,084 Kms **Good No:** 24951622 VIN: MPBUMFF50KX20830: Next Service: 161,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

2 Minor stone crack on windscreen crater area. Canopy hatch strut (Right side) is missing. Canopy key is missing.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	5
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

06 Jun 2024 Inspected by: Yuki Itohara Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
9	.5	mm
9.5		mm
		mm
9.5		mm
	Yes	
·		
·		
<i>V V V</i>		
·		
·		
·		
·		
<i>V V V</i>		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
	/ / / / / / / / / / / / / / / / / / /	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: