


<b>Make:</b> Holden	<b>Model:</b> Commodore	<b>Body Style:</b> Sedan
<b>Year:</b> 2019	<b>Registration:</b> MAF869	<b>Reg Expiry:</b> 06 Mar 2025
<b>WoF Expiry:</b> 05 Mar 2025	<b>Odometer:</b> 246,168 Kms	<b>Good No:</b> 24953263
<b>VIN:</b> W0VZM6ECXK102071	<b>Next Service:</b> 261,000kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Small stone crack in middle of windscreen. Holes in both front corners of front bumper & two holes in both rear corners of rear bumper. Holes in interior trim on rear tailgate. Two R/T aerial base fitted to roof panel.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

**Interior Comments**

Seats	Good
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments**

Screw holes in top of dashboard, screw holes in top & left side of centre console. Screw holes & hole in cup holder base in centre console. Three holes in left front floor panel. Drivers seat belt webbing worn on drivers seat belt. Non factory boot floor panel & left side boot trim panel.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5.0	mm	
Right front	5.4	mm	
Left rear	6.5	mm	
Right rear	6.5	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Jason Young

Date: 31 Oct 2024

I have read and understood this condition guide. Name: ..... Signature: .....