

## **Basic Vehicle Condition Guide**

Report ID: 24,954,103

Pass

1

Version: 1

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition

Created: 25 Nov 2024


Fail

N/A

Make: Model: Holden Colorado **Body Style:** Utility Year: 2018 Registration: LFW184 Reg Expiry: 06 Mar 2025 WoF Expiry: **Odometer:** 07 Mar 2025 136,261 Kms **Good No:** 24954103 VIN: MMU148FK0JH64545( Next Service: 143,000kms Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Small stone crack in right side of windscreen. Paint clear coat peeling off right front wing mirror cover.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No

Jason Young

Kms:

Performance	~			
Radiator / Hoses (visual)	liator / Hoses (visual)			
<b>Fransmission</b>				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes		•		
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	s)	
Left front	5	.0	mm	
Right front	5	.0	mm	
Left rear	5	.5	mm	
Right rear	6	.0	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)			~	
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	

I have read and understood this condition guide.

lame:			

25 Nov 2024

Reversing camera