

Report ID: 24,954,594 2 Version: 09 Jan 2025 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2020	<b>Registration:</b>	NBZ263	Reg Expiry:	28 Mar 2025	Engine	•		
WoF Expiry:	24 Sep 2025	Odometer:	227,936 Kms	Good No:	24954594	Oil level	~		
VIN:	MPBUMFF50LX268645	Next Service:	229,000kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
N						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection phor to	purchase and ti	lis can be analiged to		narge.	Coolant condition	~		
			P SC P SC		PT SC	Performance	~		
Key: S = scratch						Radiator / Hoses (visual)			
						Transmission			
R = rust SC PR						Operation	~		
PT = paint defect						Noise	~		
C = crack					SC	Clutch			~
P = pin dent						CV joints	<		
* = decals SD SD SD SD						Wheel bearings	۲		
W = significant scuffs						Brakes			
	S PT SC	$\sim$	Р			Performance	<		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	<		
						Tyres (lowest observed tread depth of tyres)			
Front badge is cracked. Right front door seal is torn. Canopy rear door seal is torn.						Left front	3.	.0	mm
Rear bumper left side alignment required.						Right front	0.	.0	mm
						Left rear	4.	.5	mm
Conditions During Body Inspection: Dry						Right rear	9.0 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Cood					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Yuki Itohara Date: 11 Dec 202									
Inspected by: Yuki Itohara Date: 11 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....