

Report ID: 24,954,644 12 Version: 12 Dec 2024 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MHB508	Reg Expiry:	28 Feb 2025	Engine	1		I
WoF Expiry:	24 Aug 2025	Odometer:	178,857 Kms	Good No:	24954644	Oil level	~		
VIN:	MMAJLKK10KH015107	Next Service:	184,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						. ,	Transmission		
D = dent	ssc dl			the	EID S	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack				+	S P	Clutch	•		~
P = pin dent	Ho					CV joints	~		V
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs									
		Notorcom				Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	nayed in the diagram	Hand Brake	 		
Canopy and roof rack keys are missing.						Tyres (lowest observed tread depth of tyres)			
Driver's seat base pad is worn, torn.						Left front	7.0 mm		
Right front floor carpet is worn, torn. Right sill front step paint is worn.						Right front	7.0 mm		-
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
Under Corriges & Under Despetition Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
Carpets	A					Tail lights	~		
	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dealahaa						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Yuki Itohara Date: 12 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: