


Make: Holden	Model: Commodore	Body Style: Sedan
Year: 2019	Registration: MCD415	Reg Expiry: 15 Apr 2025
WoF Expiry: 16 Apr 2025	Odometer: 252,579 Kms	Good No: 24955000
VIN: W0VZM6ECXK1033740	Next Service: ?	Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- * = decals
- SC = stone chips
- W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Holes in all corners of front & rear bumpers. Two R/T aerial bases fitted to roof panel. Left side of front grille is cracked with a large hole in it. Left side of front bumper is not clipping upto guard correctly. Spare tyre is under inflated to fit in spare wheel well. Large dent in left rear sill

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Damage to left rear mud flap.

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Hole in fabric on back rear of drivers seat. Edges are worn on webbing of drivers seat belt. Drivers door seal is damaged & torn. Screw holes in dashboard, top & left side of centre console. Bolts holes in left front floor area, has been sealed up. Aftermarket boot floor panel. Front number plate is damaged

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	4.0	mm	
Right front	3.8	mm	
Left rear	3.0	mm	
Right rear	3.0	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Jason Young

Date: 10 Jan 2025

I have read and understood this condition guide. Name: Signature: