

Report ID: 24,955,207 2 Version: 07 Jan 2025 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	Registration:	NHQ832	Reg Expiry:	08 Mar 2025	Engine		I	
WoF Expiry:	14 Mar 2025	Odometer:	83,059 Kms	Good No:	24955207	Oil level	~		
VIN:	JMFXDGG3WLZ001488	Next Service:	85,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		P SC SC		S D	Performance	~		
Key:		-0	P SC SC	-01-	30	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC D SW						Operation	~		
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dle				74114	CV joints	~		
* = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	ection Comments	Note: som	ne defects & blemishes	s may not be disp	olayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Right door mirror repeater has moisture.(operating) Extensive minor pin dents on left quarter panel.						Left front	3.5 mm		mm
Extensive finite printer son being dates print. Extensive stone chips on bonnet and right front guard.						Right front	3	3.5 r	
No spare tyre but factory puncture kit in boot.						Left rear	3.5 1		mm
Conditions During Body Inspection: Dry						Right rear	3.5 mm		mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	-		
Seats	Good					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd C					Wipers (front & rear)		~	
	rd Good					Window winder FL	~		
	• · · · · · · •					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Rear wiper	needs new blade.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
Enging Ti	ning Machanism	Time in a	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing									~
Evidence	or Carri Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Yuki Itohara Date: 06 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: