

Basic Vehicle Condition Guide

Report ID: 25,001,293


Version:

Created: 30 Aug 2024

Make: Model: Nissan Lafesta **Body Style:** Wagon Year: 2011 Registration: PQB955 Reg Expiry: 11 Sep 2024 WoF Expiry: **Odometer:** 07 Aug 2024 143,264 Kms **Good No:** 25001293 VIN: 7AT0DH7DX22102636 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Headlights are faded. Rear bumper poor fit.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

. Vehicle has belly pans. Runs on 91 octane fuel. Requires serpentine belt

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Poor | | | |
| Carpets | Poor | | | |
| Panels | Poor | | | |
| Dashboard | Poor | | | |

General Comments

Remote nw. Drivers window stuck in 1/2 open position. Air conditioning works but poorly. Heater and reverse camera work. Vehicle is literally full of rubbish and stuff so unable to gain access to everything. Rear wiper no blade

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

09 Aug 2024 Inspected by: Gary Adams

Name:

| | Pass | Fail | N/A | | |
|------------------------------|-----------------|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\triangle \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | deptl | of tyre | es) | | |
| Left front | 4 | 1.0 | mm | | |
| Right front | (*) | 3.0 | mm | | |
| Left rear | 73 | 3.0 | mm | | |
| Right rear | | 1.0 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | > | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | \(\times \) | | | | |
| Dashboard warning lights | > | | | | |
| Wipers (front & rear) | | ~ | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | | ~ | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | \(\times \) | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ~ | | |
| Number of keys | 1 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |
| | | | | | |

Signature: