

Basic Vehicle Condition Guide

Report ID: 25,006,365


5 Version:

12 Dec 2024 Created:

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2021 Registration: NWW778 Reg Expiry: 28 Feb 2025 **Odometer:** WoF Expiry: 05 Nov 2025 132,320 Kms **Good No:** 25006365 VIN: MR0AA3DD200052814 Next Service: 135,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tested battery and passed at time of inspection

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Air conditioning and heating systems along with reverse camera and navigation work fine at inspection time

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

20 Nov 2024 Gary Adams Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>V V</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | > | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 7 | .0 | mm |
| Right front | 7 | .0 | mm |
| Left rear | 3 | .0 | mm |
| Right rear | 3.0 | | mm |
| Spare | | Yes | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | • |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | V V | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 4 | | • |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | ~ | | |
| Reversing camera | ~ | | |
| | | | |

Signature: