

Report ID: 25,006,656 Version: 2 05 Dec 2024 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A	
Year:	2021	Registration:	QRA633	Reg Expiry:	25 Dec 2024	Engine	1	I	L	
WoF Expiry:	28 May 2025	Odometer:	123,697 Kms	Good No:	25006656	Oil level	~			
VIN:	MNAUMFF50MW1505	Next Service:	125,000kms	Service Histor	y: Yes	Smoke & fumes	~		<u> </u>	
						Performance	~		<u> </u>	
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
					D	Performance	~			
Key:		-0		500-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
R = rust				20		Operation	~			
PT = paint defe	ect NP					Noise	~			
C = crack				TTX.		Clutch			~	
P = pin dent	HP				2416	CV joints	~			
* = decals	- dle	10		10	SD SD	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vi significari		C	S		S D R	Performance	~			
Body Inst	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front	12	2.0	mm	
						Right front	12.0		mm	
						Left rear	11	11.0		
Conditions During Body Inspection: Dry						Right rear	11.0		mm	
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Tested batt	ery and failed at time of	inspection. Afte	rmarket suspension fi	tted.		Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	marks					Head lights	~			
Carpets	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	scratches	scuffs marks				Dashboard warning lights	~			
Dashboa	scratches				Wipers (front & rear)	~				
						Window winder FL	~			
Cault						Window winder FR	~			
General Comments						Window winder RL	~			
Driver exterior door lock appears to be damaged/broken as cannot get key in. Air conditioning and heating along with reverse camera work fine at inspection time						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~		<u> </u>	
						CD (basic test only)	L		~	
						Number of keys	1	1		
Road Conditions During Test Drive: Dry Central locking										
En alma Ti		T ian in a (Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~	
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	Inspected by: Gary Adams Date: 27 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: