

Report ID: 25,007,292 2 Version: 07 Jan 2025 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JFD630	Reg Expiry:	13 May 2025	Engine	1		1
WoF Expiry:	13 Sep 2025	Odometer:	207,842 Kms	Good No:	25007292	Oil level	~		
VIN:	MR0EZ12G404159609	Next Service:	222,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	DSC	-0	D*SC D*SC		D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sscw 6/6			The	E D SC	Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch	~		
P = pin dent						CV joints			~
* = decals SC PP						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs D SC D * SC D * SC D SC									
		Notes as				Performance	<b>v</b>		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<u> </u>	
Amber light on roof held in place with tape. Rear bumper out of alignment.						Tyres (lowest observed tread depth of tyres)			
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear	8.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Battery pass	sed test at time of inspe	ection				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	V		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
A/c working during inspection. No reverse camera or nav. Centre console cup holder assembly broken						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	1
Road Conditions During Test Drive:     Wet     Central locking							~		
Remote locking							~		
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only							·		~
Evidence of Cam Belt Replacement: Yes Kms: 161,000									~
	-								-
Inspected	d by: Reuben Harvey					Date: 12 Dec 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....