

Report ID: 25,007,450 2 Version: 10 Jan 2025 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MNA51	Reg Expiry:	28 Feb 2025	Engine	1		L
WoF Expiry:	11 Dec 2025	Odometer:	166,421 Kms	Good No:	25007450	Oil level	~		
VIN:	MMAJLKL10KH006147	Next Service:	172,000kms	Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
					6.66	Performance	~		
Key:	IS SC	-0	S D * SC S D SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		•
* = decals SRSC 919 SDSC						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC S SC						Performance			
						Hand Brake	~		
Body Inspection Comments							-	ofture	
Front bumper appears to have trim missing. Front bumper poor fit						Tyres (lowest observed tread depth of tyres)			
						Left front		7.0 m	
						Right front	8.		mm
						Left rear	6.	-	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Tested battery and passed at time of inspection						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	marks,					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	scratches	scuffs marks				Dashboard warning lights	~		
Dashboa	and the second					Wipers (front & rear)	~		
Dastibua	rd scratches					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Air conditioning and heating systems along with reverse camera work at inspection						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
ц									
Inspected by: Gary Adams Date: 17 Dec 2024									
I have read and understood this condition guide. Name:									