

Basic Vehicle Condition Guide

Report ID: 25,007,631


Version:

Created: 20 Dec 2024

Make: Ssangyong Model: **Actyon Sport Body Style:** Utility Year: 2014 Registration: HPR777 Reg Expiry: 19 Oct 2022 WoF Expiry: **Odometer:** 20 Apr 2024 270,385 Kms **Good No:** 25007631 VIN: KPADA1E6SEP209782 **Next Service:** overdue Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Headlights faded. Requires Ih tail light. LHR window won't go up unless you manually pull upwards at same time as operating switch

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Battery dead, had to jumpstart every time. Brake fluid low. Requires front brakes

<u>Interior Comments</u>			
Seats	marks		
Carpets	Average		
Panels	scratches scuffs marks		
Dashboard	scratches		

General Comments

Steering wheel off centre and pulls to curb. Lh mirror doesn't work properly. Air conditioning doesn't work but heating ok at time of inspection

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 20 Dec 2024

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch	~			
CV joints			~	
Wheel bearings	~			
Brakes				
Performance		~		
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	4	.0	mm	
Right front	5	.0	mm	
Left rear	5.0		mm	
Right rear	5.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance		~		
Shock absorbers	~			
Air Conditioning / Heater				
Operation		~		
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	\(\triangle \)			
Dashboard warning lights	~			
Wipers (front & rear)		~		
Window winder FL	~			
Window winder FR	~			
Window winder RL		~		
Window winder RR		~		
Rear view mirrors		~		
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature: