

Basic Vehicle Condition Guide

Report ID: 25,021,370


Version: 3

Created: 03 Oct 2024

Make: Model: Mazda CX-5 **Body Style:** SUV Year: 2019 Registration: MJZ912 Reg Expiry: 16 Mar 2025 WoF Expiry: **Odometer: Good No:** 03 Oct 2025 77,899 Kms 25021370 VIN: JM0KF4WLA00317329 Next Service: 87,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Fitted with a brand new windscreen while at Turners.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4wd

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Scratches in glove box	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Vasanthakumar Mayilswamy Inspected by:

	024
Fail	N/A
	1
	~
of tyre	L
)	mm
))	mm
))	mm
))	mm
Yes	
103	
	<u> </u>
	Ι
	~
_	

I have read and understood this condition guide.

Name:

Signature: