


| | | |
|--------------------------------|---------------------------------|--------------------------------|
| Make: Toyota | Model: Hilux | Body Style: Utility |
| Year: 2019 | Registration: MHS234 | Reg Expiry: 24 Sep 2024 |
| WoF Expiry: 10 Aug 2024 | Odometer: 65,629 Kms | Good No: 25051185 |
| VIN: MR0KA3CD50122823 | Next Service: 70,000 kms | Service History: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- * = decals
- SC = stone chips
- W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Centre caps missing from all wheels, dents and gouge left running board
Canopy door needs refitted, right front step plate worn

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Leak from transmission / drive shaft

Interior Comments

| | |
|-----------|---------------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | holes in dash |

General Comments

Partial service history online

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 2.5 | mm | |
| Right front | 2.5 | mm | |
| Left rear | 3 | mm | |
| Right rear | 2 | mm | |
| Spare | | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

Inspected by: Dean Sinclair

Date: 29 Jul 2024

I have read and understood this condition guide. Name: Signature: