


<b>Make:</b> Ford	<b>Model:</b> Transit	<b>Body Style:</b> Van
<b>Year:</b> 2015	<b>Registration:</b> JBJ843	<b>Reg Expiry:</b> 14 Jan 2025
<b>WoF Expiry:</b> 16 Jun 2025	<b>Odometer:</b> 159,008 Kms	<b>Good No:</b> 25052929
<b>VIN:</b> WF0XXXTTGXEM4847	<b>Next Service:</b> 187,000kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Fuel flap damaged. L/R door frame cracked. L/H cant rail damaged.  
R/H tail light chipped. R/H wing mirror not retracting.  
L/R door seal missing. Chipped windscreen.  
L/H wing mirror indicator lens cracked. High stop light cracked.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Dents, scratches, panel damage in cargo area.
Dashboard	Average

**General Comments**

L/R door step, sill, frame & floor damaged.  
L/H plastic sill moulding damaged.  
6 speed manual diesel LWB high roof van.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	4	mm	
Right front	5	mm	
Left rear	4	mm	
Right rear	6	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Daryll Timms

Date: 20 Aug 2024

I have read and understood this condition guide. Name: ..... Signature: .....