


<b>Make:</b> Renault	<b>Model:</b> Master	<b>Body Style:</b> Van
<b>Year:</b> 2018	<b>Registration:</b> LPA89	<b>Reg Expiry:</b> 30 Aug 2025
<b>WoF Expiry:</b> 01 Dec 2024	<b>Odometer:</b> 83,085 Kms	<b>Good No:</b> 25053564
<b>VIN:</b> VF1MAF5VE58604849	<b>Next Service:</b> 83,000kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

- Tow hook cover missing.
- Right wing mirror indicator lens cracked.
- Rear door handle lock surround missing.
- R/R body moulding damaged, cab corner mouldings missing.
- Detachable tow bar, tongue missing.
- Rear side door seals missing.
- One hub cap missing.

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments**

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Scratches, scuffs & panel damage in cargo area.
Dashboard	Glove box catch not working.

**General Comments**

- No sound from radio.
- Service overdue.
- Service light on.
- Long wheelbase, high roof, diesel van.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6	mm	
Right front	6	mm	
Left rear	5	mm	
Right rear	6	mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Daryll Timms

Date: 27 Aug 2024

I have read and understood this condition guide. Name: ..... Signature: .....