

Basic Vehicle Condition Guide

Report ID: 25,086,784


Version: 2

Created: 03 Oct 2024

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2017 Registration: KRM287 Reg Expiry: 04 Jan 2025 WoF Expiry: **Odometer:** 05 Jul 2025 104,280 Kms **Good No:** 25086784 VIN: MPATFR85JHT002602 Next Service: 114,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Scratches both front step plates

Both inner wheel arch chips, minor dents and scratches.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | interior handle surrounds scratches and chips | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

02 Oct 2024 Inspected by: Dean Sinclair Date:

Name:

| | Pass | Fail | N/A | |
|--|----------------------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | <i>V V</i> | | | |
| Clutch | ~ | | | |
| CV joints | | | ~ | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 6. | .0 | mm | |
| Right front | 6. | .5 | mm | |
| Left rear | 6. | .0 | mm | |
| Right rear | 5.5 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | V | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | V V V V V V | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 3 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | | |
| Reversing camera | V | | | |
| | | | | |

Signature: