

Basic Vehicle Condition Guide

Report ID: 25,087,242


Version: 3

Created: 14 Oct 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2019 Registration: MDY246 Reg Expiry: 30 Nov 2024 WoF Expiry: **Odometer:** 08 May 2025 168,928 Kms **Good No:** 25087242 VIN: MMU148EK0KH65370 Next Service: 181,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left quarter guard liner damaged Sill step plates worn, scratches and minor dents Spider rust on roof

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

09 Oct 2024 Inspected by: Dean Sinclair Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		Ι
Hand Brake	V		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	1	.0	mm
Right front	6.5		mm
Left rear	5.0		mm
Right rear	2.5		mm
Spare	Yes		
Suspension		103	
Suspension performance	'		Т
Steering performance	~		
Shock absorbers	V		
Air Conditioning / Heater			
Operation Operation			Т
Electrical / Accessories			
Head lights			1
Tail lights	<i>V</i>		
Indicators	V		
	V		
Dashboard warning lights	V		
Windowsia dos 51	~		
Window winder FL	V		
Window winder FR	'		
Window winder RL	'		
Window winder RR	/		
Rear view mirrors	<i>'</i>		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	/		

Signature: