

<b>Make:</b> Toyota	<b>Model:</b> Hilux	<b>Body Style:</b> Utility
<b>Year:</b> 2013	<b>Registration:</b> HAB64	<b>Reg Expiry:</b> 05 Aug 2025
<b>WoF Expiry:</b> 08 Oct 2025	<b>Odometer:</b> 183,524 Kms	<b>Good No:</b> 25087578
<b>VIN:</b> MR0FZ22G401073695	<b>Next Service:</b> 192,000kms	<b>Service History:</b> Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Chipped windscreen.

<b>Conditions During Body Inspection:</b> Dry
---

<u>Under Carriage &amp; Under Bonnet Inspection Comments</u>
--

<u>Interior Comments</u>	
Seats	Average, fitted seat covers.
Carpets	Average
Panels	Average
Dashboard	Average

<u>General Comments</u>	
4x4 manual diesel d/cab ute.	

<b>Road Conditions During Test Drive:</b> Dry
---

<b>Engine Timing Mechanism:</b> Cambelt	<b>Evidence of Cam Belt Replacement:</b> Yes	<b>Kms:</b> 152,076
---	--	---------------------

<b>Inspected by:</b> Daryll Timms
-----------------------------------

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	<input checked="" type="checkbox"/>		
Smoke & fumes	<input checked="" type="checkbox"/>		
Performance	<input checked="" type="checkbox"/>		
Noise	<input checked="" type="checkbox"/>		
<b>Cooling System</b>			
Coolant condition	<input checked="" type="checkbox"/>		
Performance	<input checked="" type="checkbox"/>		
Radiator / Hoses (visual)	<input checked="" type="checkbox"/>		
<b>Transmission</b>			
Operation	<input checked="" type="checkbox"/>		
Noise	<input checked="" type="checkbox"/>		
Clutch	<input checked="" type="checkbox"/>		
CV joints	<input checked="" type="checkbox"/>		
Wheel bearings	<input checked="" type="checkbox"/>		
<b>Brakes</b>			
Performance	<input checked="" type="checkbox"/>		
Hand Brake	<input checked="" type="checkbox"/>		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	9	mm	
Right front	9	mm	
Left rear	9	mm	
Right rear	9	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	<input checked="" type="checkbox"/>		
Steering performance	<input checked="" type="checkbox"/>		
Shock absorbers	<input checked="" type="checkbox"/>		
<b>Air Conditioning / Heater</b>			
Operation	<input checked="" type="checkbox"/>		
<b>Electrical / Accessories</b>			
Head lights	<input checked="" type="checkbox"/>		
Tail lights	<input checked="" type="checkbox"/>		
Indicators	<input checked="" type="checkbox"/>		
Dashboard warning lights	<input checked="" type="checkbox"/>		
Wipers (front & rear)	<input checked="" type="checkbox"/>		
Window winder FL	<input checked="" type="checkbox"/>		
Window winder FR	<input checked="" type="checkbox"/>		
Window winder RL	<input checked="" type="checkbox"/>		
Window winder RR	<input checked="" type="checkbox"/>		
Rear view mirrors	<input checked="" type="checkbox"/>		
Radio (basic test only)	<input checked="" type="checkbox"/>		
CD (basic test only)	<input checked="" type="checkbox"/>		
Number of keys	2		
Central locking	<input checked="" type="checkbox"/>		
Remote locking	<input checked="" type="checkbox"/>		
Sat. Nav. (basic test only)			<input checked="" type="checkbox"/>
Reversing camera	<input checked="" type="checkbox"/>		

<b>Date:</b> 15 Oct 2024
--------------------------

I have read and understood this condition guide. Name: ..... Signature: .....