

Report ID: 25,088,141 Version: 4 18 Nov 2024 Created:

Signature: .....

Make:	Nissan	Model:	Lafesta	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	NFW558	Reg Expiry:	18 Jul 2025	Engine			1
WoF Expiry:	25 Nov 2025	Odometer:	109,849 Kms	Good No:	25088141	Oil level	~		
VIN:	7AT0DH7DX20102781	Next Service:	119,000 Kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	sc sc		sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			ZIS	HIL	Operation	~		
R = rust PT = paint def	ect NP			$\prod$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				ᅰЦ	CV joints	~		
* = decals	sc 916			-No-	D SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs P SC S		P SC SC			Performance	~		
Dadulu	action Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	d depth	of tvre	l s)
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear			
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Dem -1-	Average, F	RF window switch	n panel loose			Dashboard warning lights	<i>v</i> <i>v</i>		
Panels						Wipers (front & rear)	<i>v</i> <i>v</i>		
Dashboa	rd Good					Window winder FL	<i>v</i> <i>v</i>		
						Window winder FL Window winder FR	<i>v</i> <i>v</i>		
General C	Comments					Window winder PK			
						Window winder RL Window winder RR	レ レ		
						Rear view mirrors	-		
							V 		
						Radio (basic test only)	<b>v</b>		
						CD (basic test only)	<b>v</b>		
			_			Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		
-	of Cam Belt Replac	-	lot Applicable	Kms:		Sat. Nav. (basic test only)			~
	or cam bert neplac			11113.		Reversing camera	~		
Inspected by: Daryll Timms Date: 22 Oct 2024									

I have read and understood this condition guide.

Name: .....