

## **Basic Vehicle Condition Guide**

Report ID: 25,088,847

Pass

Version: 1

Engine

Created: 01 Nov 2024


Fail

N/A

Make: Model: Holden Colorado **Body Style:** Utility Year: 2017 Registration: KJT648 Reg Expiry: 25 Jun 2024 **Odometer:** WoF Expiry: **Good No:** 13 Nov 2024 253,272 Kms 25088847 VIN: MMU148LK0HH62733 Next Service: 262,000km **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Stone chips in windscreen. Bonnet protector is broken.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Underbody surface rust.

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Inspected by:

Front parking sensors beeps occasionally when there is nothing near it.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No Kms:

Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	3	mm
Right front	4	.5	mm
Left rear	2.5		mm
Right rear	2.5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	1		
Number of keys Central locking	1		
	_		

Blair Robertson I have read and understood this condition guide.

Name: .....

Signature: .....

01 Nov 2024

Reversing camera