

Basic Vehicle Condition Guide

Report ID: 25,089,240


Version: 2

Created: 26 Nov 2024

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2021 Registration: NPR449 Reg Expiry: 13 Jan 2025 WoF Expiry: **Odometer: Good No:** 05 Jul 2025 41,043 Kms 25089240 VIN: KMHS281KSMU38169 Next Service: 52,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Caleb Spicer Lee Date: 13 Nov 2024

| | _ | 1 | _ | | |
|------------------------------|--------------|-----------|-----|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | V V V | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | \(\times \) | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | deptl | h of tyre | es) | | |
| Left front | 6 | 5.0 | mm | | |
| Right front | 6 | 5.5 | mm | | |
| Left rear | 3 | 3.0 | mm | | |
| Right rear | 4 | 1.0 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | v | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | | ~ | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ン ン ン | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ~ | | |
| Number of keys | 2 | 1 | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | · | | |
| Reversing camera | ~ | | | | |
| <u> </u> | | 1 | | | |

I have read and understood this condition guide.

Name:

Signature: