

Report ID: 25,089,860 Version: 1 20 Nov 2024 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A	
Year:	2015	<b>Registration:</b>	JAT834	<b>Reg Expiry:</b>	26 Dec 2024	Engine				
WoF Expiry:	24 Mar 2025	Odometer:	259,444 Kms	Good No:	25089860	Oil level	~			
VIN:	MR0FZ22G401087516	Next Service:	267,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
	D SC		P SC S P		S D SC	Performance	~			
Key:	D3C	-0			3030	Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	Transmission			
D = dent R = rust				710	HIVSD	Operation	~			
PT = paint def	ect NP				17111	Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	HIP				74116	CV joints	~			
* = decals	s sc 916			To .	ED SP	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S D S P SC P SC SC						Performance	~			
Body Incr	Dection Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments Grille broken.						<b>Tyres</b> (lowest observed tread depth of tyres)			<u>-</u> 2s)	
R/F door & L/R door seals damaged.						Left front 5 m			mm	
Right cab corner dented & scratched.						Right front		7	mm	
						Left rear	e		mm	
Conditions During Body Inspection: Dry						Right rear	6	5	mm	
						Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories	1		4	
Seats	R/F seat w	orn & ripped, L/F	seat pocket damaged	l.		Head lights	~			
	Average					Tail lights	~			
Carpets	riveluge					Indicators	~			
Panels	Screw hole	es on console.				Dashboard warning lights	~			
		lder face damag	jed, S / wheel worn.			Wipers (front & rear)	~			
Dashboa	rd	act face damay				Window winder FL	~			
	•					Window winder FR	~			
General Comments						Window winder RL	~			
4x4 diesel a	uto d/cab ute.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 15	50,209	Reversing camera	~			
							1			
Inspected by: Daryll Timms Date: 20 Nov 2024										

I have read and understood this condition guide.

Name: .....

Signature: .....