

Basic Vehicle Condition Guide

Report ID: 25,090,730


Version: 2

Created: 10 Dec 2024

Make: Model: Ford Ranger **Body Style:** Utility Year: 2020 Registration: NCR380 Reg Expiry: 19 Jan 2025 WoF Expiry: **Odometer:** 20 Oct 2025 194,088 Kms **Good No:** 25090730 VIN: MNAUM2F50LW0607: **Next Service:** 198,000km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LF wheel centre cap is missing.

Right sill panel dented. Rear canopy door damaged & has been repaired poorly.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Sump guard dented.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Glove box is broken & falls onto floor when opened.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Blair Robertson Date: 04 Dec 2024

Name:

| | Pass | Fail | N/A | | |
|------------------------------|--------------|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | ~ | | | | |
| Performance | \(\times \) | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | • | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | • | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 3.0 | | mm | | |
| Right front | 2.5 | | mm | | |
| Left rear | 4.5 | | mm | | |
| Right rear | 5.0 | | mm | | |
| Spare | Yes | | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | V | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | \(\times \) | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | | | ~ | | |
| Window winder RR | | | ~ | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ~ | | |
| Number of keys | 2 | 1 | - | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |
| • | | | | | |

Signature: