

|   |         |  | Steering performance        | ~ |   |
|---|---------|--|-----------------------------|---|---|
|   |         |  | Shock absorbers             | ~ |   |
|   |         |  | Air Conditioning / Heater   |   |   |
|   |         |  | Operation                   | ~ |   |
| Interior Comments                                     |         |  | Electrical / Accessories    |   |   |
| Seats   | Average |  | Head lights                 | ~ |   |
| Correcto  |         |  | Tail lights                 | ~ |   |
| Carpets   | Average |  | Indicators                  | ~ |   |
| Panels Cargo blind missing.                           |         |  | Dashboard warning lights    | ~ |   |
|   |         |  | Wipers (front & rear)       | ~ |   |
| Dashboard   | Average |  | Window winder FL            | ~ |   |
|   |         |  | Window winder FR            | ~ |   |
| <u>General Comments</u>                               |         |  | Window winder RL            | ~ |   |
| AWD petrol auto SUV.                                  |         |  | Window winder RR            | ~ |   |
| One key remote pad damaged.                           |         |  | Rear view mirrors           | ~ |   |
|   |         |  | Radio (basic test only)     | ~ |   |
|   |         |  | CD (basic test only)        | ~ |   |
|   |         |  | Number of keys              | 2 |   |
| Road Conditions During Test Drive: Dry                |         |  | Central locking             | ~ |   |
|   |         |  | Remote locking              | ~ |   |
| Engine Timing Mechanism: Timing Chain                 |         |  | Sat. Nav. (basic test only) |   | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: |         |  | Reversing camera            | ~ |   |
|   |         |  |                             |   |   |

Inspected by: Daryll Timms

Date: 13 Dec 2024

I have read and understood this condition guide.

Name: .....