

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MHS238	Reg Expiry:	25 Mar 2025	Engine		1	
WoF Expiry:		Odometer:	104,309 Kms	Good No:	25090931	Oil level	~		<u> </u>
VIN:	MR0KA3CD401228584	Next Service:	105,000km	Service Histor	y: Yes	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		
This report is	a guide only. Consid	eration is made	for age and milea	ge. Parts have not	been dismantled or	Noise	~		
diagnostic te a full mechan	sting undertaken. The nical inspection prior to	vehicle has beer purchase and th	ı driven up to 50kn nis can be arrangeo	n/h from cold. The ' d for an additional c	Vendor recommends harge.	Cooling System		i	1
						Coolant condition	~		
Key:	SC SC		P	SC	SC	Performance	~		
S = scratch		$\sim$		<u>5(0)</u> -		Radiator / Hoses (visual)	~		
D = dent					AN SDR	Transmission			
R = rust	s c sc			-10	HULSON	Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	sc dl			-	~###\$	CV joints	~		
* = decals		A O		70	E P	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
Jiginiculi	SC SC			SC	SC	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Left cab corner is dented. Left running board bent.						Left front	8	.0	mm
Lett running	g bourd bent.					Right front	7	.5	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	7	.5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Coverate						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	Average, l	noles drilled in da	sh.			Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Canopy door locks not working.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
			_			Remote locking	~		
-	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspecte	d by: Blair Robertson					Date: 09 Dec 20	24		
inspecte	a by. Sian hobertson								

I have read and understood this condition guide.

Name: .....

Signature: .....