

Report ID: 25,106,720 Version: 1 13 Nov 2024 Created:

Signature: .....

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	MRQ600	<b>Reg Expiry:</b>	02 Aug 2025	Engine	•		
WoF Expiry:	22 Jan 2025	Odometer:	249,067 Kms	Good No:	25106720	Oil level	~		
VIN:	7AT0H60FX20020549	Next Service:	259,000 kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		1
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
			D		D	Performance	~		1
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch	TE				Tan	Transmission	1	1	4
D = dent R = rust		1		710	HIV	Operation	~		
PT = paint defe		F I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		-
C = crack					R	Clutch			~
P = pin dent	DIG HID				74116	CV joints	~		
* = decals	DSC 916			-Jos		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant			D			Performance	~		
Body Incr	portion Commonts	Note: son	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front	mm		
						Right front		9	mm
						Left rear		9	mm
Conditions During Body Inspection: Wet						Right rear		7 m	
Conditions During Body inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rwd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		1
Panels	Cargo area	a interior panel s	cratches			Dashboard warning lights	~		1
	, Good					Wipers (front & rear)	~		1
Dashboa	rd					Window winder FL	~		1
	1					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		1
						Radio (basic test only)		~	1
						CD (basic test only)		~	1
						Number of keys	1	r	
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
	-					Remote locking	~		1
-	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 16	50,403	Reversing camera			~
								1	
Inspected	d by: Vasanthakumar	Mayılswamy				Date: 13 Nov 20	24		

I have read and understood this condition guide.

Name: .....