

Basic Vehicle Condition Guide

Report ID: 25,106,921


Version: 3

Created: 12 Dec 2024

Make: Model: Nissan X-Trail **Body Style:** SUV Year: 2021 Registration: NGE454 Reg Expiry: 21 Dec 2024 WoF Expiry: **Odometer: Good No:** 04 Sep 2025 70,873 Kms 25106921 VIN: JN1JBAT32A0059485 **Next Service:** 80,000km **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Windscreen stone chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

•

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Rowan Fey Date: 10 Dec 2024

Name:

| | Pass | Fail | N/A | | |
|---|--------------|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 8.0 | | mm | | |
| Right front | 8.0 | | mm | | |
| Left rear | 5.0 | | mm | | |
| Right rear | 5.0 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | ı | | | |
| Suspension performance | ~ | | | | |
| Steering performance | \(\sigma \) | | | | |
| Shock absorbers | ' | | | | |
| Air Conditioning / Heater | | 1 | | | |
| Operation | • | | | | |
| Electrical / Accessories | | | 1 | | |
| Head lights | • | | | | |
| Tail lights | • | | | | |
| Indicators | \(\times \) | | | | |
| Dashboard warning lights | • | | | | |
| Wipers (front & rear) Window winder FL | | | | | |
| Window winder FR Window winder FR | <i>v</i> | | | | |
| Window winder RL | - | | | | |
| Window winder RR | V | | | | |
| Rear view mirrors | V | | | | |
| | | | | | |
| Radio (basic test only) CD (basic test only) | V | | | | |
| Number of keys | 2 | | | | |
| Central locking | 2 V | | | | |
| Remote locking | V | | | | |
| Sat. Nav. (basic test only) | <i>y</i> | | | | |
| Reversing camera | ~ | | | | |
| eversing curriera | | | | | |

Signature: